



Fig. 2




FIG. 3





FIG. 4

GONDOLA CAR

25



192.168.0

BASE  
SITE







FIG. 4




FIGURE 5


Larry Sosa  
19328 W. Level St.  
Corona, Ca  
91723

PORT CHANNEL

CONDO A  
CAR

20  
TAG

42  
LOCAL STORE  
CLIENT  
92-168.0



RFID Scanner

16




Camera  
192.168.0.4

15

Wireless Access Point

14


Could handeling  
Camera  
also



Wireless Link

16

27




Wireless Lan

34



Wireless Link

33



DATABASE

SERVER

BASE SITE

128

F16.6

TOEFTT E20E5660






FIG. 7


attraction site  
recreational site

# Ski Action PictureYou™ Process





TOEYTT' E20E5660



Ski Lift  
PictureYou™ Process






FIG. 10

TOP SECRET

# General Scenic PictureYou™ System



# Attraction Ride PictureYou™ Process



# Cruise Ship PictureYou™ System

Trigger mechanism  
could include infrared  
beam, motion  
detector, timer,  
biometrics, RFID etc.

